Saia-Burgess Controls Ltd.
Bahnhofstrasse 18 I CH-3280 Murten I Switzerland
T +41 (0)26 672 71 11 I F +41 (0)26 670 44 43

saia-burgess
Smart solutions for comfort and safety

Technical Communication 04122 :

A series of connectors for PCD1/PCD2 require more force than usual to be plugged in and out

Dear Sir/Madam,

During November 2004 a series of connectors for PCD1/PCD2 were used in production, that require more force to be plugged on or removed from the board than usual.

Corrective actions have been taken immediately to ensure that deliveries that left the company after November 29, 2004 are OK again.

Please note the following:

- all connectors that have been delivered in November ensure a good electrical contact, so no replacement is necessary to ensure proper operation
- connectors that require more force can be removed using a screw driver as a lever



place the screwdriver here to remove the connector from the board

- if a customer is not willing to keep the connectors that require more force, you can order free of charge replacement connectors in Murten using the reference “Free of charge PCD1/PCD2 connectors”. The order numbers of the different variants of connectors can be found in the transfer price list

Best regards

Saia-Burgess Controls AG
Technical Customer Service

i.V. Jürg Hurni